


***AUTOMOTIVE***



**BOBINAS**

**DQ-2001 Replaces:**

XW4U-12A366-AC

**DQ-2002 Replaces:**

FORD:  
F6DZ 12029 EA  
12A336-AB  
12029-A 12029-AA  
FORD 96-99  
MERCURY 98-99

**DQ-2009 Replaces:**

JAGUAR  
4443006  
8033236  
LUCAS  
42533D  
90002444

**DQ-2010 Replaces:**

MB 029700-8040

**DQ-2003 Replaces:**

F7TZ-12029-AB  
IL2U-12029-AA  
IL2Z-12029-AA  
F7TU-12A336-BA  
F7TZ-12029-BA  
F7TZ-12029-CC  
F7TZ-12029-CA  
F7FTU-12A336-AB  
DG491 DG467  
DG472 DG508  
FORD TUUCK 97

**DQ-2004 Replaces:**

XW4U-12A366-BB  
2W4Z-12029-BA  
FORD Dg515

**DQ-2011 Replaces:**

NEC 100730  
MB029700-8230  
12V GCL209

**DQ-2012 Replaces:**F6T567  
5X05**DQ-2005 Replaces:**

F7LZ-12029-AC  
F7LZ-12029-AA  
F7LZ-12029-AD  
IF3Z-12029-AA  
2C6Z-12029-AA

**DQ-2006 Replaces:**

3L3E-12A366-CA  
7B2702  
3L3Z-12029-BA

**DQ-2013 Replaces:**

JEEP  
56028136AF

**DQ-2014 Replaces:**

RENAULT  
7700875000  
7700107177  
7700113357  
0040100052  
8200208611  
029700-8291  
SAGEM  
21595273-2  
2526181A

**DQ-2007 Replaces:**

FORD:  
3L3E-12A366-CA  
4M5G-12A366-BC  
4M5G-12A366-BB  
4M5G-12A366-BA  
1224925 13114271 1322402

**DQ-2008 Replaces:**

FORD:  
BA-12A336-A  
3R2U-12A366-AA

**DQ-2015 Replaces:**

BOSCH 0986221001  
BERU 0040100052  
RENAULT 7700875000  
8200154186 8200405098  
8200568671  
2.0CC  
OPEL 4408389 4413233  
81159986  
NISSAN 22448-00QQA  
22448-6N011

**DQ-2016 Replaces:**

RENAULT 77 0847 5000  
DENSO 029700-8291  
77 00 107 177  
77 00 133 357  
BERU  
0 045 100 052  
MANTIME TURBO 2.3L 120KW 2001  
Clio 1.1 1.4 16V 7072KW  
1.5L 18V 79KW  
Clio 1.8L 18V 2.0L 18V 124KW  
LAGUNA 1.5 16V 79KW  
1.8L 16V 80KW 2.0L 16V 103KW  
MEGANE 1.6L 16V 78KW 1.8L 16V 85KW  
KANGOO 1.8L 18V 70KW

<p><b>DQ-2017</b> ▲ <b>Replaces:</b></p> 	<p>PEUGEOT 597077 597094 FIAT 966440 1880 PEUGEOT CITROEN 9633001580 PEUGEOT 406 807 407 807 RENAULT 9833001580</p>	<p><b>DQ-2018</b> ▲ <b>Replaces:</b></p> 	<p>Chang an Star JL474Q SC6350B</p>	<p><b>DQ-2025</b> ▲ <b>Replaces:</b></p> 	<p>MITSUBISHI H6T60271</p>	<p><b>DQ-2026</b> ▲ <b>Replaces:</b></p> 	<p>NISSAN 33400-65J0 MITSUBISHI ML2 H6T11371</p>
<p><b>DQ-2019</b> ▲ <b>Replaces:</b></p> 	<p>LIONCEL MD382907 382913 325048 FI0762</p>	<p><b>DQ-2020</b> ▲ <b>Replaces:</b></p> 	<p>NISSAN 22448 31U11 22448 31U00 22448 31U01</p>	<p><b>DQ-2027</b> ▲ <b>Replaces:</b></p> 	<p>NISSAN 22448 91F00</p>	<p><b>DQ-2028</b> ▲ <b>Replaces:</b></p> 	<p>MITSUBISHI 475-9007 33400-65G01</p>
<p><b>DQ-2021</b> ▲ <b>Replaces:</b></p> 	<p>NISSAN 22448 31U11 22448 31U00 22448 31U01</p>	<p><b>DQ-2022</b> ▲ <b>Replaces:</b></p> 	<p>NISSAN 22433-60U02 HANSHIN MCP-300 12V</p>	<p><b>DQ-2029</b> ▲ <b>Replaces:</b></p> 	<p>CW-723219 MG1.6L</p>	<p><b>DQ-2030</b> ▲ <b>Replaces:</b></p> 	<p>MD325052</p>
<p><b>DQ-2023</b> ▲ <b>Replaces:</b></p> 	<p>NISSAN 22448 31U08 22448 31U16 22448 31U05</p>	<p><b>DQ-2024</b> ▲ <b>Replaces:</b></p> 	<p>HANSHIN AIC-3102G 22448 8J115 5816 22448-8J111</p>	<p><b>DQ-2031</b> ▲ <b>Replaces:</b></p> 	<p>CW-723220 MG1.6L MD325052</p>	<p><b>DQ-2032</b> ▲ <b>Replaces:</b></p> 	<p>CW-724632 VARKA1.1L 33400-65G00 33400-65G01 33410-77E01 S37000067PG HYUNDAI 9C19-0370 SUZUKI -99</p>

**DQ-2033 Replaces:**

MD 363552

**DQ-2034 Replaces:**

NISSAN  
22448-6J901  
CM11-206

**DQ-2041 Replaces:**

MITSUBISHI  
33410-77E20 77E21  
33410-77E22  
88921380,E52A

**DQ-2042 Replaces:**

NISSAN  
22448-2Y001  
22448-2Y000  
22448-2Y010

**DQ-2035 Replaces:**

NISSAN  
22448-4M500  
CM11-205  
BERU 0040102021

**DQ-2036 Replaces:**

NISSAN  
22448 5H300

**DQ-2043 Replaces:**

NISSAN  
22433-59S11  
HANSHIN  
MCP-200

**DQ-2044 Replaces:**

SF-DIS-001

**DQ-2037 Replaces:**

NISSAN  
22448-2Y005  
22448-2Y006  
22448-2Y007  
22448-2Y015  
MCP-2850

**DQ-2038 Replaces:**

GENUINE  
MD 362907  
DIAMOND  
FL 0162 3Z05  
MITSUBISHI  
CW T23219  
LANCER

**DQ-2045 Replaces:**

TOYOTA  
90919-02244  
90919-02243  
90080-19023

**DQ-2046 Replaces:**

TOYOTA  
90919-02230  
88921382 E593

**DQ-2039 Replaces:**

MITSUBISHI 4G 18  
099700-048

**DQ-2040 Replaces:**

HANSHIN  
MCD-400  
NISSAN  
22433-30P00

**DQ-2047 Replaces:**

TOYOTA  
90919-02215  
90919-19012

**DQ-2048 Replaces:**

TOYOTA  
90919-02240  
90919-T2003  
90080-19021

**DQ-2049** **Replaces:**

TOYOTA  
90919-02239  
DQG 131  
TOYOTA AVAION  
08/1999-12-2004  
90080-19019  
90080-19015  
90919-T2002

**DQ-2050** **Replaces:**

TOYOTA  
90919-02189  
029700-6850

**DQ-2057** **Replaces:**

LF86 18 100  
099700-0981  
K4238  
5808

**DQ-2058** **Replaces:**

CM11-109  
4909 C  
HITACHI

**DQ-2051** **Replaces:**

TOYOTA  
90919-02212  
029 700 7951  
88921337,E589  
TOYOTA 95-02 95-98

**DQ-2052** **Replaces:**

TOYOTA 90919-02213  
029 700 7941  
TOYOTA 95-98  
88921357,E590

**DQ-2059** **Replaces:**

CM11-108  
4X19 C  
HITACHI

**DQ-2060** **Replaces:**

CM11-110  
5Y30C  
HITACHI  
5215C PW-004

**DQ-2053** **Replaces:**

DENSO  
90048-52126  
099700-0570

**DQ-2054** **Replaces:**

90048-52130  
DIAMOND  
FK0099 12V  
8116

**DQ-2061** **Replaces:**

HITACHI  
099700-070  
099700-115R  
30520-PNA-007

**DQ-2062** **Replaces:**

TC-25A

**DQ-2055** **Replaces:**

90048-52117  
DIAMOND  
FK0026 12V

**DQ-2056** **Replaces:**

DENSO  
19070-BZ040  
JK099700-0990

**DQ-2063** **Replaces:**

TC-27A

**DQ-2064** **Replaces:**

TC-28A

**DQ-2065** **Replaces:**

MAZDA  
FFY1-18-100  
323  
FP85-18-100C

**DQ-2066** **Replaces:**

FML 1.6  
MAZDA  
ZZY1-18-100  
BP6D-18-100A

**DQ-2073** **Replaces:**

BOSCH  
0221 604 014

**DQ-2074** **Replaces:**

PASSAT  
BORA  
AUDI  
06B 905 115H,  
06B 905 115  
06A 905 115  
06B 905 115G  
06B 905 115J  
06B 905 115H  
06B 905 115L

**DQ-2067** **Replaces:**

KIA  
OK 013 18 100

**DQ-2068** **Replaces:**

HYUNIL  
27301-38020  
BOSCH 0896 221 019  
BERU ZS 252

**DQ-2075** **Replaces:**

POLO 036 905 100B  
VOLKSWAGEN  
SKODA

**DQ-2076** **Replaces:**

AUD/VW  
06B905115  
06B905115B  
06B905115E  
HITACHI CM11-201  
AUDI A3 A6 A8 TT  
PASSTA 1.8  
BERU  
0040402009

**DQ-2069** **Replaces:**

0324-6-22194  
HYUNDAI  
27301-23400

**DQ-2070** **Replaces:**

0118-6-21278  
HYUNDAI  
27301-37410

**DQ-2077** **Replaces:**

8D, 0074445, A  
ELDOR 78300001  
57F3 1 2 10/05

**DQ-2078** **Replaces:**

BOSCH  
2111-3705010  
F 000 Z50 211

**DQ-2071** **Replaces:**

HYUNIL  
27301-38020

**DQ-2072** **Replaces:**

F-722  
DIAMOND  
3017817

**DQ-2079** **Replaces:**

06C 905 115B  
BAK DE S3  
BREMI 11963ESM

**DQ-2080** **Replaces:**

077 905 115F

**DQ-2081 ▲ Replaces:**

06F 905 115A

**DQ-2082 ▲ Replaces:**

07C 905 115

**DQ-2089 ▲ Replaces:**

AUDI 058 905 105  
VOLKSWAGEN  
058 905 101  
058 905 105  
AUDI  
A6 AVANT 86 PLUS QUATTRO AHK  
04/96 12/97  
A8 58 PLUS QUATTRO AHK  
04/96 02/97  
A8 3.7 AEW 07/95 12/98  
A8 3.7 AKJ 06/97 12/98  
A8 3.7 QUATTRO AEW AKJ  
07/95 11/98

**DQ-2090 ▲ Replaces:**

BOSCH 0221504480  
FIAT 46777287  
BERU 00401000321

**DQ-2083 ▲ Replaces:**

066 905 100

**DQ-2084 ▲ Replaces:**

022 905 100A  
022 905 100B

**DQ-2091 ▲ Replaces:**

BOSCH 0221004 014  
FIAT 46467542 60510590  
BERU 25311  
LANCIA KAPPA, FIAT, BRAVO, COUPE

**DQ-2092 ▲ Replaces:**

FIAT 46777286 55180004  
CHAMPION BAE 403B  
FIAT LANCIA 14 V  
MARELLI BAE 403B

**DQ-2085 ▲ Replaces:**

NEC000070 000110  
14V  
BAE 403 H

**DQ-2086 ▲ Replaces:**

ALFA ROMEO  
60562701  
BOSCH  
0 221 504 456  
FIAT  
60562701  
60B10690

**DQ-2093 ▲ Replaces:**

0 221 504 016  
TOYOTA  
80080-19017

**DQ-2094 ▲ Replaces:**

ZS 0009  
A 000 150 17 80  
BERU  
0 040 100 039  
06T124 2

**DQ-2087 ▲ Replaces:**

LAND ROVER NEC101010L  
ROVER NEC101010  
BMW  
3 320i M 52 B (20 B 53) VANOS 03/98 09/00  
3 320i M 52 B (20 B 53) VANOS 09/90 02/98  
3 320i M5422651 09/00  
3 323i M 52 B 25 (VANOS) 03/98 09/00  
3 323i 2.5 M 62 B 25 (VANOS) 03/95 02/98  
3 325i M5425655 09/00  
3 325i X1 M5425655 09/00  
3 328i M 52 B 25 01/95 02/98  
3 328i M 52 B 25 02/98 06/00  
3 330i M6430653 06/00

**DQ-2088 ▲ Replaces:**

BMW  
01 1959-1990 BMW M3  
BOSCH 0 221 731 884  
BMW  
3 320i M 52 B (20 B 51), M 50 B (20 B 52)  
3 325i M 52 B 25, M 52 B 25 (VANOS)  
BMW 0345  
3 CABRIOLET 320i M 50 B (20 B 52) VANOS  
10/93 04/99  
3 CABRIOLET 325i M 52 B 25 (VANOS)  
03/93 03/95  
3 CABRIOLET M3 3.0 S 50 B 30 01/94 10/95  
3 COUPE 320i M 50 B (20 B 51), M 50 B (20 B 52)  
3 COUPE 325i M 52 B 25 (VANOS) 03/92 04/99  
3 COUPE M3 3.0 S 60 B 30 01/93 11/95  
3 COUPE M3 3.0 S 60 B 30 10/92 01/96  
3 M3 3.0 S 50 B 30 06/91 09/95  
5 220i 24V M 50 B (20 B 51), M 50 B (20 B 52)  
5 225i 24V M 50 B 25 05/99 02/05

**DQ-2095 ▲ Replaces:**

NEC 000120 5009  
0040 100 501 0000  
BERU KOREA

**DQ-2096 ▲ Replaces:**

**DQ-3001 Replaces:**

8ND538, D540, D555, 1103605  
1103646, 1103662, 1103683  
1103744, 1103745, 1103746  
10466391, 10472401, 10497771  
10495121  
ISUZU 8-10468-391-0  
GM 88-94 GC-71  
CADILLAC 87-88, 93-98  
CHEVROLET 87-98  
BUICK 88-98  
OLDSMOBILE 88-98  
PONTIAC 87-88  
ISUZU 92-94

**DQ-3002 Replaces:**

JEEP 213BJC  
CHRYSLER 90-95  
CHEROKEE 91-97  
DODGE 90-95  
JEEP 91-97  
PLYMOUTH 91-95  
CP-32 4751253  
4797293 5234210  
5234610 5252577  
C506 19017110  
SHADOW 91-94  
SPIRIT 91-95

**DQ-3009 Replaces:**

12321405, 12336833, 19017194  
F-503, F-1953  
DG-325, DG-325A, DG-325ADP  
DG-434, DGE-453  
E1EF 12029 AA, E2EF 12029 AA  
E2FZ 12029 A, F515-18-10X  
E3EF 12029 AA, E3FZ 12029 A  
E73F 12029 AA, E3Z2 12029 A  
E73F 12029 AB, E73Z 12029 A  
1684979-C1, F515-18-10X  
ZZM1-18-100, ZZM4-18-100  
FORD 83-97 LINCOLN 84-94  
MAZDA 84-97 MERCURY 82-95  
FORD GL

**DQ-3010 Replaces:**

JEEP 4762312  
JEEP 91-93

**DQ-3003 Replaces:**

GM D-523, D-530, D-532  
8131936, J8131936  
1875894, 1985473, 10497132  
CONP 12029 A, IDO-4002S  
DGG-419, 1684825-C1, 5-71  
WIRES - RED AND YELLOW  
AMERICAN MOTORS 80-81  
BUICK 77-87, CADILLAC 74-90  
CHECKER MOTORS 75-82  
CHEVROLET 74-87 374-89  
GM 74-89 JEEP 80-81  
OLDSMOBILE 75-87  
PONTIAC 75-87

**DQ-3004 Replaces:**

GM D524, D531, D535  
1876209, 1986474, 1988908  
WIRES - RED AND WHITE  
BUICK MODELS V6/V8 74-90  
CADILLAC  
MODELS V6/V8 75-95  
CHECKER 81  
CHEVROLET  
MODELS V6/V8 75-76; 77-91  
CHEVROLET  
GM 75-76; 77-85  
GM 77-86  
GMV8-403 75-76; 78-86  
OLDSMOBILE  
MODELS V6/V8 74-90

**DQ-3011 Replaces:**

56028172  
DODGE 98-2001  
JEEP 98-2001

**DQ-3012 Replaces:**

FORD 8 9 220 061 726  
9 220 061 710  
FALCON EA, EB  
FORD LTD FE 4, 1-84-88  
FORD LTD DA DB DC 3, 9, 4, 0-8, 8

**DQ-3005 Replaces:**

GM D-535, D-537, D-544  
D-560, D-573, 83501871  
8983501871, 1115315, 1115317  
1115466, 1115468  
1115491, 10477208  
ISUZU  
8-01115-315-0, 8-01115-466-0  
806673T, 817378T  
ASUNA 90-93  
BUICK 85-88; 91-95  
CADILLAC 85-86; 90-95  
CHEVROLET 85-95 85-97  
GM 85 87 GEO 89 93

**DQ-3006 Replaces:**

GM  
D-535, D537, D544, D-560, D573  
1115315, 1115317, 1115466, 1115468  
1115491, 10477208  
83501871 8983501871  
ISUZU  
8-01115-315-0, 8-01115-466-0  
806673T, 817378T  
ASUNA 80-93, BUICK 85-88 91-95  
CADILLAC 85-86 90-95  
CHEVROLET 85-86, GEO 89-93  
CHEVROLET TRUCK 85-97  
JEEP 85-86, GMC TRUCK 85-9  
ISUZU 87-94, PASSPORT 88-90  
OLDSMOBILE 85-86 90-95  
PONTIAC 85-95

**DQ-3013 Replaces:**

FORD  
F8QV-12029B, F8QZ-12029B, F8QZ-12029B  
DGF437, DGF438, DGF443  
M2794  
F316-18-100, F316-18-100A, F316-18-100A  
F316-18-100, F316-18-100A, F316-18-100  
F316-18-100, F316-18-100A, F316-18-100  
F316-18-100, F316-18-100, F316-18-100  
F316-18-100, F316-18-100, F316-18-100  
SUZUKI 30410-04910  
MITSUBISHI J810072, J810072, J810072  
DIAMOND F-265, F-267, F-268  
LUCAS BL-1400  
FORD 88-92  
MERCURY 84-92  
SUZUKI 89-94  
M479A 323 86-95

**DQ-3014 Replaces:**

D-577, 10489421  
ISUZU 8-10458-421-0  
BUICK 95  
CADILLAC 96  
CHEVROLET 96-97  
CHEVROLET 96-99  
96-99  
ISUZU 97  
OLDSMOBILE 96-97  
PONTIAC 96-97

**DQ-3007 Replaces:**

GM D-525, D-527, D-528  
D-529, 1187847, 8134003  
J8134003, 1116444, 1115445  
1115447, 1115448, DGG-421, 5-73  
1115465, DGG-222, DGG-322  
5-74, IDO-4003, IDO-4003A  
AMERICAN MOTORS 82-83  
BUICK 75 76; 81-84  
CADILLAC 82-84  
CHEVROLET 75-84; 82-84  
CHEVROLET 75-77  
GM 75-77; 82-84; JEEP 82-84  
OLDSMOBILE 75-77; 81-84  
PONTIAC 75-77; 80-84

**DQ-3008 Replaces:**

GM D535, D537, D544, D575,  
1115313, 1115317,  
1115468, 1106013, 10477944  
ISUZU 8-01115-315-0,  
8-01115-466-0  
DIAMOND F-616  
ANC 8983501871  
OLDSMOBILE 85-95  
PONTIAC 85-95  
BUICK 85 88; 91 93  
CADILLAC 85-86; 90-95  
PRODUCTS 85-94  
JEEP 85-87  
ISUZU 87-94

**DQ-3015 Replaces:**

GMD-550 D-547 D-583  
10457109 10472748 10474461  
10497477 D-542 D-583  
BUICK 88-88  
CHEVROLET 90-98  
OLDSMOBILE 87-88  
PONTIAC 88-99

**DQ-3016 Replaces:**

BOSCH  
0221505437  
0221505438  
MERCEDES  
0001500480  
0001500580  
0001586803  
A0001500480  
A0001586803

<p><b>DQ-3017</b> <b>Replaces:</b>             JAGUAR DAC 4608            BAE 504 DK            JAGUAR 91-95</p>	<p><b>DQ-3018</b> <b>Replaces:</b>             VW/AUDI            0585 10457730 19005218            CADILLAC            2002-2004 ESCALADE            2003-2004 ESCALADE ESV            2002-2004 ESCALADE EXT            CHEVROLET            2002-2004 1999-2004            2003-2004 2000-2004</p>	<p><b>DQ-3025</b> <b>Replaces:</b>             FREECA 33410-85120            F-076            SUZUKI MIC-2000 GC-5            FTM-063T            SUZUKI            DAIHATSU            TOYOTA            FTM-063GT            GC-5 MIC-2000</p>	<p><b>DQ-3026</b> <b>Replaces:</b>             370501B2            JL368Q, SC7080            Auto JI368</p>
<p><b>DQ-3019</b> <b>Replaces:</b>             12556450            12558940            D580</p>	<p><b>DQ-3020</b> <b>Replaces:</b>             GM 12568062            ISUZU 8-12568-062-0            STANDARD UF-303            BUICK RAINIER 05-04            CHEVROLET LIGHT TRUCK            COLORADO 06-04            CHEVROLET LIGHT TRUCK            TRAILBLAZER 05-02            GMCLIGHTTRUCK ENVOY 05-02            OLDSMOBILE BRAVADA 04-02            HUMMER H3 06            ISUZU ASCENDER 05-03            IPIKUP 07-08 SAAB 9-7 05</p>	<p><b>DQ-3027</b> <b>Replaces:</b>             3705010A4 DQ126A            JL485Q2, SC6350A</p>	<p><b>DQ-3028</b> <b>Replaces:</b>             SUZUKI 33410A60D30</p>
<p><b>DQ-3021</b> <b>Replaces:</b>             VW POINTER, GOL, VERONA            FORD AF5FU 12029AA            FORD ESCORT</p>	<p><b>DQ-3022</b> <b>Replaces:</b>             MD131711, MD098964            MD104696            MD113551, MD141004,            27301-35020            F504 C509 KIAKMD160532            MD166146, 19017117            805024, 805041            DLJ217, DLJ227            MITSUBISHI V33 V73</p>	<p><b>DQ-3029</b> <b>Replaces:</b>             FA0004, MD309455            MITSUBISHI V31</p>	<p><b>DQ-3030</b> <b>Replaces:</b>             MD102315, 19017127, E-550            F-100,            80 5023, DLJ219            DODGE 87-89            MITSUBISHI 87-89</p>
<p><b>DQ-3023</b> <b>Replaces:</b>             3705010-01            JL472Q, SC6350            SC6350            DQ 125</p>	<p><b>DQ-3024</b> <b>Replaces:</b>             CW608874            DELICA</p>	<p><b>DQ-3031</b> <b>Replaces:</b>             MITSUBISHI MD 339027            DIAMOND F-809            MITSUBISHI (MOTOR) - 98            4G64            DELICA</p>	<p><b>DQ-3032</b> <b>Replaces:</b>             MD338169:            FREECA            MITSUBISHI            DN64401703171 DLK/FLK</p>

**DQ-3033 Replaces:**

NISSAN  
22433-51E15

**DQ-3034 Replaces:**

NISSAN  
15017-173, E-671, DG-450, DG-464  
NISSAN FTM-087A1  
80 5045, DLJ 127  
22433-08000, 22433-08001  
22433-08010, 22433-51J10  
22433-53J20, 22433-55810  
22433-55E11, 22433-56E12  
22448-18861, 22448-55E12  
22448-85E00, 22448-55E11  
22433-KA080, 22448-OC801  
22448-D4300  
FORD F3XA 12029 AA  
F3XY 12029 A, F5XZ12029 AA  
MERCURY 83-88  
NISSAN-DATSUN 88-98  
SUBARU 88-92

**DQ-3041 Replaces:**

HITACHI  
21DC  
NISSAN CMIT-216A

**DQ-3042 Replaces:**

H3T024, F-898  
MITSUBISHI  
MAZDA

**DQ-3035 Replaces:**

19017022, E-354, 22433-12P00  
94138768, 22448-54A10  
E-534, 80 5077, L1108, 22433-16R10  
22433-12P01, 22433-2P10  
22433-12P11, 22448-16R10  
22448-81A00, 22448-81A10  
22448-80W00, 22448-80W10  
22448-90W00, 22448-90W10  
DAEWOO DD 96320815, 96338522  
HITACHI CM1T-205  
ISUZU 8-24136-765-0  
CPFL 4284028  
ISUZU 88-89  
NISSAN-DATSUN 84-87  
KIA KK137-18-10K,  
KK137-18-10XC

**DQ-3036 Replaces:**

NISSAN-DATSUN 88-89  
19017126, E-540, 80 5055  
DLJ 254, 22433-03G01  
22433-03G10, 22433-03G11  
22433-10G10, 22448-18G10  
22448-03G01, 22448-03G11  
22448-04G01, 22448-04G03  
22448-04G11, 22448-10G00  
22448-10G10, 22448-04G10  
22448-11G00, 22448-11G10  
22448-29R10, 22448-04501  
22448-04505, 22448-04506  
22448-04511, 22448-04512  
22448-04513  
22448-04515, 22448-04516

**DQ-3043 Replaces:**

H3T021 F-693

**DQ-3044 Replaces:**

MISUBISHI H3T03273  
H3T030 H3T03071A  
H3T03671  
FORD LIATA 94-95  
FORD MAZDA  
DIAMOND F-747

**DQ-3037 Replaces:**

SUZUKI  
33410-85120  
F-076

**DQ-3038 Replaces:**

HITACHI  
CM1T-231

**DQ-3045 Replaces:**

10917121, F-511, DGE-447  
FOC612029AA, B657-18-100  
B658-10-10XA, F2G8-18-10X  
F2G9-18-10X  
FORD 96  
MAZDA 90-93  
MERCURY 91-96

**DQ-3046 Replaces:**

NISSAN-DATSUN 93-97  
22433-1E400, 22448-1E400  
22448-1E410

**DQ-3039 Replaces:**

NISSAN B4  
CM1T227, 22433-F4302  
90919-02200  
NISSAN B4-88  
ISUZU 89-93  
UF596

**DQ-3040 Replaces:**

CM1T-230A

**DQ-3047 Replaces:**

NISSAN-DATSUN '93  
NISSAN 331  
NISSAN  
22433-53F00  
22433-55Y00  
22433-65Y10  
22448-1C701 \*U  
22448-37J10  
22448-37J20

**DQ-3048 Replaces:**

MAZDA 323 '89-'94  
F-558, 805044, DLJ232  
G601-18-10X, G601-18-100  
G602-18-10X, G623-18-10X

**DQ-3049 Replaces:**

MITSUBISHI MD  
18423D, MD334558  
MD152648  
DIAMOND F-608, F-648  
CHRYSLER 95-97  
DODGE 91-96  
EAGLE 95-97  
MITSUBISHI 91-97

**DQ-3050 Replaces:**

ISUZU 8-84338-923-0  
19017120, E-547  
8-94371-836-0  
805054, DLJ453  
8-8449-494-1  
HONDA 94-96  
ISUZU 88-97  
GENERAL MOTORS  
94 371 838  
HITACHI CM1T-213  
ISUZU 8-84371-838-0  
OPEL 43 04 227

**DQ-3057 Replaces:**

02506 0080  
06T05A0080

**DQ-3058 Replaces:**

TOYOTA  
19070-74170  
19500-74090 \*U  
19500-74091 \*U  
19500-74100 \*U  
90919-02209  
TOYOTA 90919-02207  
LEXUS 92-97  
TOYOTA 92-97

**DQ-3051 Replaces:**

TOYOTA  
90919-02164  
GM  
94404545, 94855695  
ISUZU 8-94404-545-0  
CHEVROLET 86-88  
GEO 89: 93-94  
ISUZU 86-89

**DQ-3052 Replaces:**

TOYOTA  
90919-02163  
94855502  
GEO 96-97  
TOYOTA 87-96

**DQ-3059 Replaces:**

S/X1.0 87-90, CX 1.3  
18V 88-90  
DAIHATSU  
90048-52056  
90048-52091  
90048-52096

**DQ-3060 Replaces:**

DAIHATSU 90048-52109-000  
D I A M O N D F - 7 1 4  
USE WITH EXTERNAL RESISTOR

**DQ-3053 Replaces:**

TOYOTA  
90919-02135, 90919-02139  
90919-02196, 90919-02152  
GM 94840127, 94847392  
NIPPON DENSO  
029700-5430, 0297005471  
0297007040  
VW J90 919 021 39  
TOYOTA 3Y 83-93  
CHEVY, NOVA 85-88  
GEO (94840127) 89-92

**DQ-3054 Replaces:**

GENERAL MOTORS 94 847 392  
029700, 5430  
94840127

**DQ-3061 Replaces:**

DAIHATSU  
90048-52101-000  
DIAMOND  
F-718

**DQ-3062 Replaces:**

DAIHATSU 19080-29121  
19080-87703  
100297-0860  
DAIHATSU-2001

**DQ-3055 Replaces:**

TOYOTA  
90919-02226  
90919-02220

**DQ-3056 Replaces:**

TOYOTA 90919-02218  
90919-02217  
BRAND: GENUINE  
TACOMA-2WD14  
88921366, 88921266  
90080-19007  
90080-19006

**DQ-3063 Replaces:**

TOYOTA 90919-02201

**DQ-3064 Replaces:**

TOYOTA 90919-02175  
90919-02188  
19500-74020, 19500-74030  
DENSO 029 700-8450  
029 700-6451  
029 700-6641  
TOYOTA 90-91

**DQ-3065 Replaces:**

19017136, E-559  
TOYOTA 90919-02185  
DENSO 0297006820  
LEXUS 400 88-92  
TOYOTA 88-93

**DQ-3066 Replaces:**

TOYOTA 19500-74040,  
19500-74050, 90919-02197  
90919-02208, 19017119  
E-546  
DENSO 029 700-7050  
029 700-7051  
J90 919 021 97  
LEXUS 90-96  
TOYOTA 90-96

**DQ3073 Replaces:**

HONDA 30500-PA-A01,  
500-P0H-A01,  
30500-POH-A01  
HONDA  
ACCORD 2001  
HONDA 30500-P0A-A01  
ACCORD CD5 94-97  
CIVIC

**DQ-3074 Replaces:**

DAEWOO  
GM D-535,D-537,D-544  
D-550,D-573,03501071,  
0993501971,1115315,1115317  
1115455, 1110468,  
1115491,10477208 1115457  
ISUZU 8066737,8173787  
8-01115-315-0,8-01115-486-0  
BUICK 85-88, 91-95  
CADILLAC 85-86, 90-95  
CHEVROLET 85-95 CHEVROLET 85-97  
GM 85-97 GEO 89-93  
ISUZU 87-84 JEEP 85-86  
OLDSMOBILE 85-86,90-95  
PONTIAC 85-85

**DQ-3067 Replaces:**

TOYOTA 90919-02015  
90919-02106,19017000  
E-533, 297004790  
TOYOTA 80-84  
86-90

**DQ-3068 Replaces:**

TOYOTA 90919-02154  
19017135, E-558  
TOYOTA 83-93

**DQ-3075 Replaces:**

DAEWOO  
33410A60B30-000  
Y35

**DQ-3076 Replaces:**

MD111950, MD114994, MD104686,  
19017112, E-569,  
F-088, 27301-24520, 27301-22000,  
80 5043, DLJ230  
EAGLE ECHIC107  
DODGE 87-92  
EAGLE 89-96  
HYUNDAI 89-94  
MITSUBISHI 87-93  
PLYMOUTH 87-92

**DQ-3069 Replaces:**

DAIHATSU  
90048-52072-000  
90048-52095-000  
DAIHATSU  
CHARADE I.0I(EU) G102 01/88  
CHARADE 1.3 -- 01/89  
CHARADE III  
1.3 I(G102)HCE 08/88 12/92  
CHARADE III  
1.3 I4WD(G102)HCE 08/88 01/93  
CHARADE III  
TRE VOLUMI 1.3 HCE 11/90 02/93

**DQ-3070 Replaces:**

PIAGGIO  
90048-52084-000  
PIAGGIO  
PORTER Planale piatto  
Autotelaio  
1.0 CB41 02/93 08/94

**DQ-3077 Replaces:**

MITSUBISHI  
DAEWOO

**DQ-3078 Replaces:**

MITSUBISHI  
MD-104696  
MD111950, MD 114994  
19017112, E-569 F-088  
HYUNDAI  
27301-32800  
27301-32810  
27301-32820 27301-24520  
27301-22000  
80 5043, DLJ230  
EAGLE ECHIC107  
DODGE 87-92 EAGLE 89-96  
HYUNDAI 89-94  
MITSUBISHI 87-93  
PLYMOUTH 87-92

**DQ-3071 Replaces:**

HONDA CIVIC  
HONDA 30500-PTO-005  
30500-P01-005  
30500-PM3-005  
30500-PM3-015  
HITACHI CM1T-209B  
CM1T-217

**DQ-3072 Replaces:**

HONDA  
ACCORD 2000  
19017118, E-545  
HONDA 30510-P73-A01  
30510-P73-A02  
30510-PT2-006  
ACURA 92-96

**DQ-3079 Replaces:**

HYUNDAI  
27301-02502  
BOSCH  
0986221006

**DQ-3080 Replaces:**

MD 098964 MD 104696  
MD 113551 MD 131711  
MD 141044 MD 160532  
MD 186146 19017117  
C-509 F-504 27301-35020  
805024 8050441  
DLJ217 LDJ227  
CHRYSLER 90-95  
DODGE 87-96  
EAGLE 91-94  
HYUNDAI 89-92  
MITSUBISHI 86-97

**DQ-3081 ▲ Replaces:**

DAEWOO 86336522  
SUSUKI  
MATTZ

**DQ-3082 ▲ Replaces:**

VOLKSWAGEN  
SANTANA2000  
BOSCH 0221 502 007,  
0221 502 008  
VOLKSWAGEN 330 905 115A

**DQ-3089 ▲ Replaces:**

AUDI VOLKSWAGEN  
6N0905104,867905104,040100 025  
867905104A,867905352  
BOSCH 0221601003,0221601004  
0221601005, 1227022030  
SEAT 6N0905104, 867905104  
SKODA 004050016, 6N0905104

**DQ-3090 ▲ Replaces:**

BOSCH 0 221 506 002  
0 221 506 003  
0 221 506 444  
0 221 506 445  
DAEWOO  
000 158 70 03  
0001587503  
MERCEDES  
000 158 70 03  
000 158 71 03  
000 158 75 03  
VOLKSWAGEN  
00A 905 105

**DQ-3083 ▲ Replaces:**

VW 867 905 104, 867 905 105A  
357905104 547905104  
701905104, 70195104A  
867905104A, 867905352  
BOSCH 0221601008  
0221601007, 0221601001  
0221601002, 0221601003  
0221601004  
LUCAS DLB 708  
VW 92-87  
SKODA 004050016

**DQ-3084 ▲ Replaces:**

CA7220  
AUDI/VW 6N0905104  
6N0905104A  
867905104A  
867905352, 54795104  
LUCAS DAB954  
SKODA 004050016  
TELEFUNKEN 339700  
BOSCH 1227022030  
1227030030

**DQ-3091 ▲ Replaces:**

BOSCH 0 221 506 002  
MERCEDES BENZ  
A 000 158 75 03

**DQ-3092 ▲ Replaces:**

BOSCH 0 221 601 012  
RENAULT T4 01 275 174  
VOLVO 1275174  
RENAULT  
SAFRANE II 2.5 20V (854F) N7U 700,  
N7U 701 07/99 12/99  
VOLVO  
850 2.0 B 5202 S 05/94 12/98  
850 2.0 B 5204 F 05/91 12/98  
850 2.0 B 5204 FS 05/91 12/98  
850 2.0 10V B 6205 F8 05/94 12/97  
850 2.0 GLT B 5204 T2 07/96 05/97  
850 2.0 Turbo B 5204 F1, B 5204 T1 05/93 12/95  
850 2.3 B 5234 FS 07/94 12/97  
850 2.3 T5 B 5234 FT 05/93 07/98

**DQ-3085 ▲ Replaces:**

VOLKSWAGEN 867905104, 867905100B,  
867905105A, 867905104, 647905104  
BOSCH 0221601005, 0221601007  
LUCAS DLB 708  
VOLKSWAGEN GOLF 92-97  
FPH ELMOTOR 86106201  
JETTA (SUDAMERICA MEXICO) 92-97  
GOLF (SUDAMERICA MEXICO) 92-97

**DQ-3086 ▲ Replaces:**

BOSCH  
0221601001  
0221601002  
AUDI/VW  
701905104  
701905104A  
867905105A

**DQ-3093 ▲ Replaces:**

BOSCH  
F 000 ZS0 104

**DQ-3094 ▲ Replaces:**

AUDI/VW 377 905 105D  
BOSCH 9220081504  
F000ZS0105

**DQ-3087 ▲ Replaces:**

AUDI/VW 357905104  
701905104, 70195104A  
867905104, 867905104A  
867905105A, 867905352  
0221601001, 0221601002  
0221601003, 0221601004  
0221601006, 0221601007  
SEAT 867905104  
SKODA 004050016  
LUCAS DLB 708

**DQ-3088 ▲ Replaces:**

BOSCH  
0221601001  
0221601002  
SET 867905105A  
VW  
701905104  
701908104A  
867905105A

**DQ-3095 ▲ Replaces:**

MARELLI 060780002010,  
060780038010, 00708035  
BAE 800 AK, BAE 800 B, BAE 800 2K  
7672015 7626232  
4854362, 48543037  
BOSCH F000ZS0103  
ALFA ROMEO 90800420 60503492  
LUCAS DLB 314  
PINTO 55-80-75

**DQ-3096 ▲ Replaces:**

MARELLI  
060780049010  
BAE 800EK  
BAE 881EK  
SEAT: SE028915 000B  
7700107269

**DQ-3097 Replaces:**

ZK RRL 1.361  
 DUCCELLIER 2526026A  
 PEUGEOT 597045, 5903525480  
 CITROEN 96035284, 597043  
 MAGNETI MARELLI  
 CQ705738010, 06705754010, BAE5078X  
 SAGEM 2526028  
 VALEO 245038, CD330  
 CITROEN  
 AK 1.0, 1.1, 1.1L, 1.3L, 1.4L, 91  
 ZX 1.1L, 1.4L, 91  
 PEUGEOT  
 105 1.0, 1.1, 1.1L, 1.4, 1.4L, 91  
 205 1.0, 1.1, 90  
 408 2.0, 90-91

**DQ-3098 Replaces:**

PEUGEOT 33002289  
 770103135, 12335238  
 U-504, 80 5034, 3287577-3  
 CHRYSLER T1031135  
 DUCCELLIER 520064, 2526023  
 2526023A  
 LUCAS DLB 204  
 MARELLI BAE 504 B  
 VOLVO 3287677-3  
 VALEO 245054, 520064A  
 CD 325, 2526023, 2526048  
 EAGLE BB-92  
 JEEP BB-92  
 RENAULT 84-80  
 VOLVO 82-89

**DQ-3105 Replaces:**

MARELLI  
 060705409010  
 607 054 09  
 BAE 504 L  
 RENAULT  
 77 00 749 450

**DQ-3106 Replaces:**

RENAULT 19 1.6 (HASTA 1995)  
 RENAULT 7702 218 586

**DQ-3099 Replaces:**

DELCO REMY 3474233, 3474282  
 GM 03474232, 03474282  
 90448740, 90510387  
 OPEL 1208002  
 1208004, 1208048  
 DUCCELLIER 2526050A  
 LUCAS DLB 305, DLB 703  
 VALEO 245043, CD339, 2526050  
 OPEL ASTRA 1.6i 91  
 CORSA 1.2, 1.3, 1.6i 82  
 KADETT 1.2, 1.3, 1.6, 1.6i 82  
 VECTRA 1.6, 1.6i 88-89  
 VAUXHALL ASTRA 1.6i 91  
 BELMONT 1.2, 1.3, 1.6, 1.6i 82  
 NOVA 1.2, 1.3, 1.6i 82

**DQ-3100 Replaces:**

DELCO REMY 3474233-3474283  
 GM 90449730, 90510386  
 DUCCELLIER 2526049, 2526049A  
 OPEL 1208003, 1208054  
 LUCAS DLB 704, 1208070  
 VALEO  
 245042, CD338, 2526049  
 OPEL ASTRA 1.4i, 1.6i 81  
 CORSA 1.2, 1.4i, 1.6i 87  
 KADETT 1.4i CAT, 88-81  
 VECTRA 1.6, 1.8 88  
 VAUXHALL ASTRA 1.4i, 1.6i 81  
 BELMONT 1.4i CAT, 89-91  
 CAVALIER 1.6, 1.8 88  
 NOVA 1.2, 1.4i, 1.6i 87  
 SAGEM 2526049, 2526049A

**DQ-3107 Replaces:**

RENAULT  
 77 00 863 020  
 77 01 041 607  
 SAGEM  
 2 526 051 A  
 2 526 110 A  
 VOLVO  
 70863020-7

**DQ-3108 Replaces:**

RENAULT  
 77 00 100 589  
 SAGEM  
 2 526 114 A

**DQ-3101 Replaces:**

DUCCELLIER 2526024A  
 PEUGEOT 597047  
 CITROEN 96041378  
 FIAT 9604137880  
 VALEO 245038, CD326  
 2526024, 2526024A  
 CITROEN XM 2.0L INJ 89  
 PEUGEOT 605 2.0, 90-91

**DQ-3102 Replaces:**

MARELLI BAE 507 AK, 80705701  
 080705738010, 80705738  
 CITROEN 97531208, 597042  
 DUCCELLIER 2526009, 2526009A  
 PEUGEOT 597042  
 LUCAS DLB 206  
 VALEO CD 321, 2526009  
 CITROEN BX 1.6L, 1.9L 83  
 PEUGEOT  
 205 1.1, 1.3, 1.4, 1.6i 88  
 309 1.1, 1.3, 1.5, 1.6 88  
 405 1.6, 1.9 87

**DQ-3109 Replaces:**

RENAULT 7700100643

**DQ-3110 Replaces:**

RENAULT  
 77 00 863 021  
 77 01 041 608  
 SAGEM  
 2 526 052 A  
 2 526 111 A  
 VOLVO  
 70863021-5

**DQ-3103 Replaces:**

FAIR 07588435, 07546875, 07703777,  
 7648975, 7746151  
 LUCAS DAC 2045, DAC 8093, DLB 802  
 MARELLI BAE 504D, BAE 504F,  
 RAE 206R, 0807054010,  
 0607054080, 06070404  
 FIAT A 2.0, TURBO 92, TEMPRA 1.4 93  
 TEMPRA  
 1.6, 1.6i 80-83, TIPO 1.4, 1.6, 1.6i 83  
 UNO 70, 1.4, 1.4i 89-92,  
 UNO 75, 1.5i CAT 89-92  
 INNOCENTI EIBA 1.4 SPI, 83, EIBA 1.6 83  
 LANCIA DELTA 1.6 MONOJETRONIC 89-94,  
 DELTA 4SPI 93  
 THEMA 2.0i 89-92 y 1.0 1.3i MPI 89  
 MARELLI 477004200  
 SAGEM 2 526 031 AFERRARI 115013

**DQ-3104 Replaces:**

DUCCELLIER 520073-520073A  
 597043, 96010513-87530780  
 597043  
 LUCAS DLB 205  
 VALEO 520073, CD 308  
 CITROEN AX 1.0L, 1.1L, 1.3L, 1.4L  
 BX 1.1L, 1.4L 83  
 PEUGEOT 205, 1.1, 1.4, 1.6i, 1.8i  
 309 1.1, 1.4, 1.6i 87  
 405 1.4, 1.9i 87

**DQ-3111 Replaces:**

LAND ROVER  
 NEC10047  
 ROVER GCL206  
 NEC10047  
 SAGEM  
 2 526 061A  
 2 526 144A  
 LAND ROVER  
 DISCOVERY II 2.0 16 V -- 05/93 06/94  
 DISCOVERY II 2.0 16 V -- 05/94

**DQ-3112 Replaces:**

MARELLI  
 607 081 38  
 BAE 801 AK  
 RENAULT  
 77 00 854 306  
 77 00 872 265

**DQ-3113****Replaces:**

MARELLI 80700154  
BAE3018V  
RENAULT 17 3008430F  
7703 872682  
RENAULT  
21 Renault 12.0 Turbo (L48, JTR 756 3030 1092  
21 Renault 12.0 Turbo (4811, JTR 756 3030 1092  
ESPACE II 3.0 (J6G) 27X 775 1195 0301  
LAGUNA 3.0 (B95E, B96) 27X 750 1195 0301  
LAGUNA 3.0 (B95E, B96) 27X 757 1195 0301  
LAGUNA Grandtour 3.0 (B95E, B96) 27X 750 3030 1092  
LAGUNA Grandtour 3.0 (B95E, B96) 27X 757 3030 1092

**DQ-3114****Replaces:**

MARELLI 84E 601 CK  
RENAULT 77 00 868 320  
77 00 872 583  
RENAULT  
ESPACE II 3.0 (J60D) 27X 775 1195 0301  
LAGUNA 3.0 (B95E/R, B96) 27X 750  
27X 755 1195 0301  
B95E/R, B96) 27X 757 1195 0301  
LAGUNA Grandtour 3.0 (K95R, K96) 27X 755  
02956 0301  
LAGUNA Grandtour 3.0 (K95R, K96) 27X 757  
02956 0301

**DQ-6001****Replaces:**

B03801



SY6480A18-ME  
SUV JEEP:  
ISUZU: 8-01101-038-0  
8-01104-038-0  
GM: 1104038, 10450424, 10460192  
OPEL: 1208051, 1104047, 380017  
1E01  
DAEWOO: 98350585, 19005252  
OPEL  
FRONTERA: 2.2i 16V 09/98  
LEGANZA: 2.2i 18V 09/98  
LANDS: 1.3i 04/97

**DQ-6002****Replaces:**

DAEWOO:  
19005265  
98253555

**DQ-3115****Replaces:**

BOSCH 0221502435  
BMW  
1990-1994, 1995, 1994, 1991-1992  
MERCEDES-BENZ  
0001585503, A0001585503  
1993 300SEL 6.3.2  
1992-1993 400SE V8 42L  
1990-1993 300SE L6 30L  
E600, E420, SL500, S500, 600SL, 500E  
400E, 500SE, 600SEL, S420, 600SEL

**DQ-3116****Replaces:**

BOSCH 0221502429  
BMW 535iL6 M30 3. 5L 1990-1993  
735i L6M30 3.5L 1990-1992  
735iL L6 M30 3.5L 1990-1992  
750iL V12 M70 3.0L 1990-1994  
750iL V12 M73 5.4L 1996  
850Ci V12 M70S 5.0L 1991-1992  
850Ci V12 M70S 5.0L 1993-1994  
MERCEDES-BENZ  
0001584503, 0001584503, 0001585503  
0001585303, 0001585403, 0001586103, 0  
001586203, 300CE L6 3.0L 1980-1993  
400E V8 4.2L 1992-1993  
420SEL V8 4.2L 1990-1991  
600E, 600SL, 600SEC, 600SEL, 600SEL  
600SL, E420, E600, E600, SL500, SL600

**DQ-6003****Replaces:**

DQG:1210  
3705010A6

**DQ-6004****Replaces:**

SY6480A18-ME  
SUV JEEP:  
ISUZU: 8-01101-038-0  
8-01104-038-0  
BM: 1104038, 10450424  
10490192  
OPEL: 1208051, 1104047  
380017, 1E01  
DAEWOO: 98350585  
OPEL:  
FRONTERA: 2.2i 16V 09/98  
LEGANZA: 2.2i 18V 09/98  
DAEWOO:  
LANOS: 1.3i 04/97

**DQ-3117****Replaces:**

HYUNDAI  
27301-24610  
27301-24620  
MITSUBISHI  
27301-24610  
27301-24620  
MITSUBISHI MD114994

**DQ-3118****Replaces:**

FIAT 07582152, 07748152, 7562152  
7663177, 7698431, 7748152, 7748154  
LUCAS DLE 800  
MARELLI BAE508, BAE508D, 80705804  
06070580010  
VALEO 2256030, 245149, CD326  
SAGEM 2526 030  
UNIPART GCL 175  
AUTOBANCHI Y 10 1000 89  
Y 10 1000 IE97, Y 10 1100 IE 90  
FIAT PANDA 1000 IE 90 TEMPRA 1400 90  
TIPO 1100 88 TIP 1400 88-89  
UNO 990, 1000, 1100, 1110 IE 89

**DQ-6005****Replaces:**

194 MUCP-POINT ENGINE  
19005265

**DQ-6006****Replaces:**

PONTIAC:  
11 038 23

**DQ-3119****Replaces:**

BOSCH  
022 504 461  
LADA  
VACO-0001, 1220 703 202  
2112-370580-10  
05-11-23280 PBT

**DQ-3120****Replaces:**

HONDA 30500-PM5-A02  
30500-PM5-A03  
19017023, E-535  
ACURA 88-89  
HONDA 88-89  
ROVER GCL181

**DQ-6007****Replaces:**

B38725



PONTIAC: 1103905, 1103872  
D553 D547  
PONTIAC: 1994  
C861, 9-3905  
PONTIAC: 92-93 10457075  
SUNBIRD: Z OL 4CIL  
CHEVY TODS:  
1.4 1.6L 4CIL 94000  
CHEVY MONZA: 97-00  
SUNBIRD: 82093  
OPEL: 12 08 063

**DQ-6008****Replaces:**

19017116, 1 549 067, 6 503 279  
5 503 280, F-313, 88F-12029-A1A  
55F-12029-A1A, 885F-12029-A2A  
528F-12029-CA, DG-435, DG-449  
DG-454, DG-457, DG-455, DG-460  
DG-461, E8TF-12029-AA, EE-03A  
E8TF-12029-A, E8TF-12029-AA  
F1VU-12029-A1A, F1VU-12029-A2A  
F1VY-12029-A, F15U-12029-AA  
F5LY-12029-A, F5OU-12029-AA  
F5OY-12029-A, F5OY-12029-B  
F5RZ-12029-C, Z7M0-10-100  
F37U-12029-AA, F37Z-12029-A  
F5OY-10-100  
DENSO 029 700 6700  
FORD 81 597 F080 48 89 LINCOLN 81 07  
MAZDA 84 97 MERCURY 91 98



**DQ-6025 Replaces:**

VW 021905106C 021905106B  
BERU 0040100 007  
ZS004  
STANDARD UF-338  
VOLKSWAGEN GTI 03-98  
VOLKSWAGEN JETTA 01-99  
BERU 0040102013 ZSE013

**DQ-6026 Replaces:**

BERU 9741 102 000 0000  
BENZ 000 150 1680

**DQ-6033 Replaces:**

VW/AUDI  
028905105  
BOSCH  
F000ZS0213

**DQ-6034 Replaces:**

BOSCH  
0 221 504 461  
2112-3705010-10  
BOSCH F000ZS0200  
GM 93248876

**DQ-6027 Replaces:**

MOTOROLA  
01R43059X01  
101R42076X01

**DQ-6028 Replaces:**

MARSHALL ME 05-01.  
MOTOROLA 01R4304R01

**DQ-6035 Replaces:**

BOSCH 2111 3745010  
LADA F000 ZSO 211

**DQ-6036 Replaces:**

BOSCH F000ZS0208 F000ZS0207  
FIAT 46752948  
FIAT SIENA 1.2 18V(EXPORT) 178 D7 055  
01/02  
FIAT(BR) PALIO 1.0i 16V 1.0 MPI 16V FIRE  
01/01  
PALIO 1.3i 16V 1.3MPI 16V FIRE  
01/00  
PALIO FAMILIARE 1.0i 16V 1.0 MPI 16V  
FIRE 01/01  
PALIO FAMILIARE 1.0i 16V 1.0 MPI 16V  
FIRE 01/01  
SIENA 1.3i 16V 1.3 MPI FIRE 01/00  
12/00

**DQ-6029 Replaces:**

CITROEN 597048  
597050  
96074054  
FIAT 9607495480  
9607405482  
9622889780  
PEUGEOT 097048 597070  
SAGEN 2526040A  
VALEO 245040 03331  
2526037A

**DQ-6030 Replaces:**

VOLKSWAGEN  
BERU 0040402008 ZSE008  
032905106D 0221503006  
0221603010  
SUDANERIKK BORA 1.0i 99  
DOLF 1.4i 2000 LUPO 1.4i 2000  
NEW BEETLE 2.0i 98  
PASSAT 2.0i 2000  
POLO 1.4i 98  
VOLKSWAGEN 032 905 106.  
032 905 106 B  
SEAT 032 905 106 B  
SKODA 032 905 106.  
032 905 106 B  
AUDI A3 1.8i 20V/ A4 1.8i 20V 98  
SEAT 2000

**DQ-6037 Replaces:**

BOSCH  
GM 93 261 953  
F 000 Zs0 201

**DQ-6038 Replaces:**

ALFAROMEO  
60558152 60586072  
60809606  
BOSCH 0221503407  
0221503457  
CITROEN 597053  
FIAT 60809606 7648797  
HONDA 30520-PDF-E01  
KIA OK011-18-100  
LAND ROVER ERR6045  
ERR6566  
PEUGEOT 597053  
VOLKSWAGEN 0489051051

**DQ-6031 Replaces:**

VOLKSWAGEN 032 905 106  
032 905 106 B  
SEAT 032 905 106 B  
SKODA 032 905 106  
032 905 106 B  
AUDIA3 1.8i 20V  
A4 1.8i 20V 98  
SEAT ALHAMBRA 2.0i 2000  
VW(BR) A4 1.6i 1.2 01/98  
VW(BR) BORA 1.6i 99  
1.4i 2000  
LUPO 1.4i 2000  
NEW BEETLE 2.0i 98  
PASSAT 2.0i 2000  
POLO 1.4i 98

**DQ-6032 Replaces:**

VOLKSWAGEN 032 905 106  
032 905 106 B  
SEAT 032 905 106 B  
SKODA 032 905 106, 032 905 106 B  
A3 1.8i 20V/A4 1.8i 20V 98  
SEAT ALHAMBRA 2.0i 2000  
(BR) A4 1.8i 1.2 01/99  
BORA 1.8i 99  
1.4i 2000  
LUPO 1.4i 2000  
NEW BEETLE 2.0i 98  
PASSAT 2.0i 2000  
POLO 1.4i 98

**DQ-6039 Replaces:**

BOSCH  
0221503407 0221503457  
ALFA ROMEO  
60558152,60809606,7648797,  
76487970,60586072  
CITROEN 597053  
FIAT 7648797,60558152,60809606  
PRUGEOT 597053  
VW 0489051050,0489051051  
LAND ROVER ERR6045,ERR6566  
ERR1 134386  
HONDA 30520-PDF-E01  
KIA 05011-18-100,OK011-18-100

**DQ-6040 Replaces:**

ALFA ROMEO  
60558152 60586072  
60809606  
BOSCH  
0 221 503 407  
0 221 503 457  
CITROEN  
5970 53  
FIAT 60809606 7648797  
HONDA 30520-PDF-E01  
KIA OK011-18-100  
LAND ROVER  
ERR6045 ERR6566 \*5  
PEUGEOT 5970 53  
ROVER ERR6045  
VOLKSWAGEN 048 905 106 1



<p><b>DQ-6057</b> ▲ <b>Replaces:</b>              PEUGEOT            206, 106, 306, 307            597072, 597074, 9828158580,            598319            CITROEN            597072, 597074, 9828158580,            96248755            SAGEM            25261174, 2526117, 2526117A            VALEO 245109</p>	<p><b>DQ-6058</b> ▲ <b>Replaces:</b>              PEUGEOT            206            PEUGEOT            597074, 598319, 597078            597079, 96358849            2526208A            WITH IGNITION MODULE</p>	<p><b>DQ-6065</b> ▲ <b>Replaces:</b>              PEUGEOT/CITROEN            597080,96363378            SAGEM            9636337880,2526182A            VALEO            245095,96363378            PEUGEOT 307 1.6L</p>	<p><b>DQ-6066</b> ▲ <b>Replaces:</b>              PEUGEOT            597073</p>
<p><b>DQ-6059</b> ▲ <b>Replaces:</b>              GM            90-536-184            9119567            09119567            OPEL            1208 008,90536 194</p>	<p><b>DQ-6060</b> ▲ <b>Replaces:</b>              125805317</p>	<p><b>DQ-6067</b> ▲ <b>Replaces:</b>              SAAB 9178955            0421A695902            55561132</p>	<p><b>DQ-6068</b> ▲ <b>Replaces:</b>              PEUGEOT            597075            94632641            96341314            96632641            FIAT            9663264180            VALEO 245098</p>
<p><b>DQ-6061</b> ▲ <b>Replaces:</b>              BOSCH            0 221 503 014            OPEL            1208306,90543059,90532618</p>	<p><b>DQ-6062</b> ▲ <b>Replaces:</b>              BOSCH            0 221 503 015            OPEL            1208012,90543253,90560110</p>	<p><b>DQ-6069</b> ▲ <b>Replaces:</b>              BOSCH            0 221 503 033            MERCEDES            0001501380</p>	<p><b>DQ-6070</b> ▲ <b>Replaces:</b>              6V87QE-3705010B            DQ3 6815A            USED ON ALL KINDS OF DIRECT SPARK            ELECTRIC SPRAY ENGINE WITH FOUR            OR SIX CYLINDER</p>
<p><b>DQ-6063</b> ▲ <b>Replaces:</b>              GM            93177212            OPEL            1208020, 24420584            BERU            ZS338            0040100338</p>	<p><b>DQ-6064</b> ▲ <b>Replaces:</b>              PEUGEOT/CITROEN            597056,962113086            9621308680,9351308680            SAGEM 2526087,2528087A            VALEO 245088            PEUGEOT 108 1.6L            CITROEN SEXO 1.6VTS</p>	<p><b>DQ-6071</b> ▲ <b>Replaces:</b>              USED FOR ALL KINDS OF IGNITION,            SYSTEM OF FOUR AND SIX CLINDER,            DIRECT IGNITION GASOLINE ENGINE.</p>	<p><b>DQ-6072</b> ▲ <b>Replaces:</b>              0221503407</p>

**DQ-6073 ▲ Replaces:**

HYUNDAI ATOS  
27301-02600

**DQ-6074 ▲ Replaces:**

HYUNDAI  
ACCENT  
27301 22600

**DQ-6081 ▲ Replaces:**

PC99-27301-26600

**DQ-6082 ▲ Replaces:**

MD 158956  
DODGE '90  
EAGLE '91-94  
MITSUBISHI '90-94  
PLYMOUTH '91-94

**DQ-6075 ▲ Replaces:**

HYUNDAI ACCENT  
2730122040

**DQ-6076 ▲ Replaces:**

DODGE '90  
EAGLE '91-94  
MITSUBISHI '90-94  
PLYMOUTH '91-94  
MD 158956  
HYUNDAI  
27301-23700

**DQ-6083 ▲ Replaces:**

FORD MOTORCRAFT  
986F-1209-AC  
FORD MONDEO

**DQ-6084 ▲ Replaces:**

HYUNDAI  
27301-22050

**DQ-6077 ▲ Replaces:**

HYUNIL  
27301-23003

**DQ-6078 ▲ Replaces:**

OK30A 1B 10X

**DQ-6085 ▲ Replaces:**

HYUNDAI  
27301-37100

**DQ-6086 ▲ Replaces:**

NISSAN  
22433AA50A  
DIAMOND  
FH0286 12V

**DQ-6079 ▲ Replaces:**

KIA-225  
6WY2809A

**DQ-6080 ▲ Replaces:****DQ-6087 ▲ Replaces:**

NISSAN  
22433AA360

**DQ-6088 ▲ Replaces:**

NISSAN  
22433AA230

	<p><b>DQ-2097</b> ▲ <b>Replaces:</b></p> <p>TOYOTA 90919-02234</p>		<p><b>DQ-2098</b> ▲ <b>Replaces:</b></p> <p>RENAULT 7700675000 7700107177 7700113357 0040100052 8200208611 029700-8291 SAGEM 21595273-2 2526181A</p>		<p><b>DQ-3122</b> ▲ <b>Replaces:</b></p> <p>BOSCH 0 221 503 035 BENZ 112 V6 F300-116246 BERU 0040100297 ZS297 BOSCH 0 221 503 012 MAN 51259190016 HUECO 138709 MERCEDES-BENZ 0001587303 0001587803 A0001587303 A0001587803 SCANIA 1789358</p>		<p><b>DQ-2104</b> ▲ <b>Replaces:</b></p> <p>EE03A 2M2E-12A366-AB</p>
	<p><b>DQ-2099</b> ▲ <b>Replaces:</b></p> <p>SKODA 06F 905115 06F 905115 C 06F 905115 B 06F 905115 A SEAT 06F 905115 F AUDI 07K 905 715 05F 905 715 D</p>		<p><b>DQ-2100</b> ▲ <b>Replaces:</b></p>		<p><b>DQ-2105</b> ▲ <b>Replaces:</b></p>		<p><b>DQ-2106</b> ▲ <b>Replaces:</b></p> <p>6R83-12A366-AA 099700-1120</p>
	<p><b>DQ-2101</b> ▲ <b>Replaces:</b></p> <p>HYUNDAI DAI 27301-26640</p>		<p><b>DQ-2102</b> ▲ <b>Replaces:</b></p> <p>瑞风</p>		<p><b>DQ-2107</b> ▲ <b>Replaces:</b></p> <p>6R83-12A366-BA N743V</p>		<p><b>DQ-2108</b> ▲ <b>Replaces:</b></p> <p>TOYOTA 90919-A2001</p>
	<p><b>DQ-2103</b> ▲ <b>Replaces:</b></p> <p>MB099700-0260 XW93-12029-AB</p>		<p><b>DQ-3121</b> ▲ <b>Replaces:</b></p> <p>H3T03973 FB0068</p>		<p><b>DQ-2109</b> ▲ <b>Replaces:</b></p> <p>TOYOTA 099700-0710 2W93-12A366-AB</p>		<p><b>DQ-2110</b> ▲ <b>Replaces:</b></p> <p>TOYOTA 90919-A2002</p>

<p><b>DQ-2110A</b> <b>Replaces:</b></p>  <p>TOYOTA 90919-A2002</p>	<p><b>DQ-2111</b> <b>Replaces:</b></p>  <p>VOLVO 1275602 MB029700-8180 13301 12V</p>	<p><b>DQ-2118</b> <b>Replaces:</b></p>  <p>6E5E-12A375-BA BO591202517</p>	<p><b>DQ-2119</b> <b>Replaces:</b></p>  <p>19070-97205</p>
<p><b>DQ-2112</b> <b>Replaces:</b></p>  <p>HANSHIN AIC-4004G 22448 6N015 2X23</p>	<p><b>DQ-2113</b> <b>Replaces:</b></p>  <p>HANSHIN AIC-6207G 22448 Ax001 3110</p>	<p><b>DQ-6089</b> <b>Replaces:</b></p>  <p>DODGE 53006565, 88921319</p>	<p><b>DQ-6090</b> <b>Replaces:</b></p>  <p>SKODA FABIA - OCTAVIA VW LUPO 4 PIN PRESA OVALE 1088033 VW 047 905 104A VW 047 905 104B CHAMPION BAE 961 AE</p>
<p><b>DQ-2114</b> <b>Replaces:</b></p>  <p>ZJ20 18 100 K5014 6608C</p>	<p><b>DQ-2115</b> <b>Replaces:</b></p>  <p>HITSUBISHI H6T12271 7825</p>	<p><b>DQ-6091</b> <b>Replaces:</b></p>  <p>GM-MOTORS OPEL</p>	<p><b>DQ-0000</b> <b>Replaces:</b></p>
<p><b>DQ-2116</b> <b>Replaces:</b></p>  <p>TOYOTA 90919-02250</p>	<p><b>DQ-2117</b> <b>Replaces:</b></p>  <p>TOYOTA 90919-C2003</p>	<p><b>DQ-0000</b> <b>Replaces:</b></p>	<p><b>DQ-0000</b> <b>Replaces:</b></p>